

* C0998, C0999

Step	Check Item	Result	Action
1	Is C0999 being shown?	YES	Perform step 3.
2	Slide out the 3rd Drawer, block PC4 with a sheet of paper, and check PC4 as follows. (See p. T-5, 6.) 1) Port: P39-3 2) Select the function "Port."		
	3) Is the data for P39-3 set to "L"?  1136T121AA	NO	Check PWB-H and flat cable and replace PC4.
		YES	First replace PF-102 PWB-A, then replace EP2050 PWB-A if necessary.
3	Unblock PC4 and check PC4 as follows. (See p. T-5, 6.) 1) Port: P39-3 2) Select the function "Port."		
	3) Is the data for P39-3 set to "H"?  1136T122AA	NO	Check PWB-H and flat cable and replace PC4.
		YES	First replace PF-102 PWB-A, then replace EP2050 PWB-A if necessary.