1-4. PARTS WHICH MUST NOT BE TOUCHED

(1) Screws

Purpose of Application of Red Paint

Red paint is applied to the screws which cannot be readjusted, set, or reinstalled in the field.
The basic rule is not to remove or loosen the screws to which red paint is applied. In addition, be advised that, if two or more screws are designated as those which must not be touched on a single part, only one representative screw may be marked with red paint.

(2) Variable Resistors on Board

Do not turn the variable resistors on boards for which no adjusting instructions are given in "ADJUSTMENT."

(3) Other Screws

Two screws on the Lens Rail



Two screws on the Lower Pre-Image Transfer Guide Plate



Two screws on the Mirror Motor Unit

