

8. Tighten the Scanner Positioning Screw which was loosened in step 3.