

	Control Signal	Energized	Deenergized	WIRING DIAGRAM
SL1	PWB-A PJ11A-6A	L	H	2-I