	Control Signal	Actuated	Deactuated	WIRING DIAGRAM
S61	PWB-A PJ26A-2	L	H	25-J
S62	PWB-A PJ26A-4	L	H	25-I
S63	PWB-A PJ26A-7	L	H	25–I
S64	PWB-A PJ26A-9	L	H	25-H

	Control Signal	Blocked	Unblocked	WIRING DIAGRAM
PC72	PWB-A PJ25A-2	L	H	25-K
PC73	PWB-A PJ25A-5	L	H	25-J