Symbol	Parts/Signal Name	Display Page	IC No.	Port No.	I/O	Operation Characteristics/Panel Display		CN/PJ No.
						H or 1	L or 0	
PC29	4th Drawer Paper Take-Up Sensor	6/8	IC2A	PB3	I	Paper not present	Paper present	PJ8A-5
PC31	Large Capacity Toner Collecting Box Set Sensor	6/8	IC2A	PC3	I	Out of position	In position	PJ2A-2
PC67	3rd Drawer Paper Lift-Up Motor Pulse Sensor	6/8	IC1A	PC1	I	Unblocked	Blocked	PJ9A-5B
PC68	4th Drawer Paper Lift-Up Motor Pulse Sensor	6/8	IC1A	PD1	I	Unblocked	Blocked	PJ9A-4A
PC69	3rd Drawer Lower Position Sensor	7/8	IC2A	PD1	I	Not at lower limit	At lower limit	PJ4A-7A
PC70	4th Drawer Lower Position Sensor	7/8	IC2A	PC0	I	Not at lower limit	At lower limit	PJ4A-8A
PWB-E1	3rd Drawer Paper Empty Board	6/8	IC1A	PC0	I	Paper not present	Paper present	PJ4A-4A
PWB-E2	4th Drawer Paper Empty Board	6/8	IC1A	PD0	I	Paper not present	Paper present	PJ4A-3A
UN5	3rd Drawer Paper Descent Key	7/8	IC2A	PC1	I	OFF	ON	PJ4A-9A
UN6	4th Drawer Paper Descent Key	7/8	IC2A	PC2	I	OFF	ON	PJ4A-10A