1156SBT040110A

## C0b## Staple Sorter/Sorter Malfunctions

| * | Code | Description | Detection Timing |
|---|---|---|---|
| | C0b00 | Transport drive malfunction | See the ST-210/S-207 Service Manual. |
| | C0b01 | | |
| | C0b10 | Paper Clamp Unit motion failure | See the ST-210/S-207, ST-101/S-104 Service Manual. |
| | C0b11 | | |
| | C0b12 | | See the ST-210/S-207 Service Manual. |
| | C0b13 | | |
| | C0b30 | Paper Aligning Mechanism drive failure | See the ST-210/S-207, ST-101/S-104 Service Manual. |
| | C0b31 | | |
| | C0b50 | Stapling failure | |
| | C0b51 | | |
| | C0b52 | | |
| | C0b53 | | |
| | C0b60 | Bin motion failure | See the ST-210/S-207, ST-101/S-104 Service Manual. |
| * | C0b61 | | |
| | C0b62 | | |
| | C0b63 | | |
| | C0b64 | | |
| | C0b65 | | |
| | C0b70 | Hole punching failure | See the ST-210/S-207 Service Manual. |
| | C0b71 | | |
| | C0b72 | | |

1156SBT040111A

## C0d## Duplex Unit Malfunctions

| * | Code | Description | Detection Timing |
|---|---|---|---|
| | C0d00 | Front/Rear Edge Guide Plates home position detection failure | See the AD-5 Service Manual. |
| | C0d20 | Gate Unit home position detection failure | |
| | C0d50 | Duplex Unit Drive Motor M31's failure to turn | |
| | C0d51 | Duplex Unit Drive Motor M31 turning at abnormal timing | |