
4-2. Troubleshooting Procedures

1156SBT040201A

1) C0000: Main Drive Motor M1's Failure to Turn
C0001: Main Drive Motor M1 Turning at Abnormal Timing

Relevant Electrical Parts	
• Main Drive Motor M1	• Master Board PWB-A



1156C05TAA