2) C0040: Suction Fan Motor M4's Failure to Turn

Relevant Electrical Parts	
• Suction Fan Motor M4	• Master Board PWB-A



1156C06TAA