4) C004A: Original Glass Cooling Fan Motor M5's Failure to Turn
C004b: Original Glass Cooling Fan Motor M5 Turning at Abnormal Timing
C004C: Ventilation Fan Motor M3's Failure to Turn
C004d: Ventilation Fan Motor M3 Turning at Abnormal Timing

| Relevant Electrical Parts | |
|---|---|
| • Original Glass Cooling Fan Motor M5<br>• Ventilation Fan Motor M3 | • Master Board PWB-A |




1156C08TAA