7) C03##: Master Board/Harness Malfunctions

Relevant Electrical Parts	
• Master Board PWB-A	• PF-205/105 Master Board PWB-A • Duplex Unit Master Board PWB-G

◆C0300 to C033C

Step	Action
1	Change Master Board PWB-A.

◆C0350, C0351

Step	Action
1	Check the connections from PJ20A on PWB-A to PJ13A on PF–205/105 PWB-A.
2	Change PWB-A or PF-205/105 PWB-A.

◆C0352

Step	Action
1	Check the connections from PJ20A on PWB-A to PJ8G on Duplex Unit Master Board PWB-G.
2	Change PWB-A, PF-205/105 PWB-A, or Duplex Unit Master Board PWB-G.

◆C0353, C0357

Step	Action
1	Check the connections from PJ20A on PWB-A to CN1A on C-301 PWB-A.
2	Change PWB-A or C-301 PWB-A.