
8) C0400: Exposure Lamp LA1's Failure to Turn ON
C0410: Exposure Lamp LA1 Turning ON at Abnormal Timing

Relevant Electrical Parts	
• Exposure Lamp LA1 • Exposure Thermal Fuse TF1	• Exposure Lamp Regulator PWB-J • AE Sensor Board PWB-H • Master Board PWB-A



1156C11TAA