
12) C0910: 2nd Drawer Upward Motion Failure

C0914: 2nd Drawer Paper Lift-Up Motor M14's Failure to Turn

C0920: 1st Drawer Upward Motion Failure

C0924: 1st Drawer Paper Lift-Up Motor M13's Failure to Turn

Relevant Electrical Parts	
• 1st Drawer Lift-Up Sensor PC65	• 1st Drawer Paper Lift-Up Motor M13
• 2nd Drawer Lift-Up Sensor PC66	• 2nd Drawer Paper Lift-Up Motor M14
• 1st Drawer Lift-Up Motor Pulse Sensor PC67	• Master Board PWB-A
• 2nd Drawer Lift-Up Motor Pulse Sensor PC68	• Power Supply Board PWB-C



1156C15TAA