
18) C0990: Main Tray Upward Motion Failure
C0991: Main Tray Downward Motion Failure
C0992: Main Tray Downward Motion Failure
C0993: Main Tray Upward Motion Failure
C0994: Elevator Motor M26's Failure to Turn

Relevant Electrical Parts	
• Main Tray Lower Position Sensor PC2 • Elevator Motor Pulse Sensor PC5 • 3rd Drawer Paper Lift-Up Sensor PC19 • Lower Limit Position Sensor PC35	• Cabinet Transport Board PWB-H • PF-105 Master Board • Main Tray Elevator Motor M26



1156C27TAA