20) C099E: Shift Gate Position Detecting Failure

C099F: Shift Gate Position Detecting Failure

C0996: 3rd Drawer Lock Release Failure

C0F79: Paper Empty Sensor Failure

Relevant Electrical Parts	
• Shift Tray Paper Empty Sensor PC1 • 3rd Drawer Paper Empty Sensor PC20 • Main Tray Paper Empty Board PWB-E	• 3rd Drawer Set Sensor PC7 • Shift Gate Position Detecting Sensor PC34 • 3rd Drawer Lock Solenoid SL41 • Cabinet Transport Board PWB-H • PF-105 Master Board PWB-A

