
21) C0d00: Duplex Unit Front/Rear Edge Guide Plate Home Position Detection Failure

C0d20: Duplex Unit Gate Unit Home Position Detection Failure

C0d50: Duplex Unit Drive Motor M31's Failure to Turn

C0d51: Duplex Unit Drive Motor M31 Turning at Abnormal Timing

Relevant Electrical Parts	
• Duplex Gate Home Position Sensor PC8 • Front/Rear Edge Guide Plate Home Position Sensor PC9	• Duplex Unit Drive Motor M31 • Gate Motor M32 • Front/Rear Edge Guide Drive Motor M33 • AD-9 Master Board PWB-G



1149C24TAA