RN SERIES TECHNICAL BULLETIN

Data Category	☐ Field Modification	■ Trouble-Shooting	☐ General Information	☐ Safety Advice

DISTRIBUTED TO : All Distributors

DATE : 12 April, 2001

MODEL : All "RN" models

ISSUE NO. : RNT-012

Our Ref.: C1-1895
C1-1896

Proceeding Grade
- ☐ Action ASAP
- ☐ Action as given below
- ■ Action if required
- ☐ Refer in need

Parts Compatibility
- ☐ Compatible
- ☐ Conditionally Compatible
- ☐ Not Compatible
- ■ Old Obsolete

Handling of Modified Parts
- ☐ Free of Charge
- ☐ Conditionally Chargeable
- ■ Chargeable

SUBJECT: 021-52504-600 CLAM/V3.00 (EPROM)
021-52505-500 CLEN/V3.00 (EPROM)

Brief:
Machine program has been changed.

Reason:
The machine asked for reconfirmation of the paper size each time the paper size on the paper feed tray was changed.

Modification:
The programming of the EPROM was changed to detect the paper size automatically, each time the paper on the paper feed tray was changed.

Newly-registered Part
021-52504-600 CLAM/V3.00 (EPROM Program) → EPROM for machines to Asian Countries.
RN2150AN, RN2050AN, RN2150AW, RN2050AW, RN2130AS, RN2030AS, RN2180C, RN2080C.

021-52505-500 CLEN/V3.00 (EPROM Program) → EPROM for machines to Europe and U.S.A.
RN2130UI, RN2030UI, RN2000UI, RN2150UP, RN2050UP, RN2150EN, RN2050EN, RN2100EP, RN2000EP, RN2150EP, RN2050EP.

NOTE:
If the machine application serial number given below is same as that for program version 2.05 (ref: bulletin issue No. RNT-011), it means that ROM version 2.05 was never installed on that machine model.

Application Serial No.

RN2130UI 85131241	RN2100EP 85150723	RN2050AW 85250367
RN2030UI 85221754	RN2000EP 85200541	RN2130AS 85140197
RN2000UI 85430682	RN2150EP 85080257	RN2030AS 85210255
RN2150UP 85070016	RN2050EP 85270208	RN2180C 85420061
RN2050UP 85280051	RN2150AN 85110025	RN2080C 85410182
RN2150EN 85090001	RN2050AN 85240195	
RN2050EN 85260001	RN2150AW 85100190	