RP Series Technical Bulletin

ISSUE NO.: RPT-002-rus.doc

MODEL: RP3xxx Series DATE: 30 March, 2001

Data Category ☐Field Modification ☐Trouble Shooting ☒General Information ☐Safety Advice

Proceeding Grade	**Parts Compatibility**	**Handling of Modified Parts**
☐Action ASAP	☐Compatible	☐Free of Charge
☐Action as given	☐Conditionally Compatible	☐Conditionally Chargeable
☒При необходимости	☐Not Compatible	☐Chargeable
☐Refer in need	☐Old Obsolete	

Our Ref. QA47-2165

SUBJECT: Установка зазора подачи краски

BRIEF:

Изменен рекомендуемый зазор между растирочным и доктор валом для барабанов серии RP с целью уменьшения подачи краски.

DETAILS:

Изменение зазора.

Старое значение	Новое значение
0.12 +/- 0.02 мм	0.10 до 0.12 мм

Action for the machines in field:

При подтекании краски в барабане необходимо проверить и при необходимости отрегулировать зазор подачи краски. Зазор должен быть менее 0,12 мм.

Application Serial Numbers:

RP3100EP	97360001~
RP3500EP	97220003, 97220005, 97220006, 97220009 ~
RP3590EP	97290003 ~
RP3700I	97130033, 97130034, 97130036, 97130038 ~
RP3700P	97120004, 97120040, 97120044, 97120045, 97120049, 97120052, 97120054, 97120055, 97120058, 97120059, 97120061, 97120063, 97120065, 97120066, 97120068, 97120071, 97120073, 97120074, 97120075, 97120076, 97120078 ~
RP3700W	97140027 ~
RP3790I	97180007, 97180008, 97180009, 97180011 ~
RP3790P	97170011 ~
RP3790W	97190003 ~
RP-A3 Inkless drum	60510541 ~
RP-LG Inkless drum	60610125 ~

Please wait for application serial numbers for the machine type not mentioned above.

Attached: