

HINT

How to search for where a signal in a circuit diagram has jumped to.

1. Press the  button, and the cursor changes to  .

2. Mark the name of the signal you want to find with [ ] marks, and press the Ctrl + C Keys.



3. Press the  key or the Ctrl + F keys to bring up the Find dialog box, then paste with the Ctrl + V keys and execute.



4. The part already marked as above will be detected, so press the  key again and execute again, or press the F3 key, to detect the point to where the signal has jumped.



5. If the following dialog box appears, click Yes without changing anything.

