2-12. C0F10: AE Sensor Board PWB-H Malfunction



1136T023AA

Symbol	Name
PWB-H	AE Sensor Board
PWB-A	Master Board

Step	Check Item	Result	Action
1	Is the voltage across PJ4AA-6 on PWB-A and GND 0.18 V or less when the Scanner is at its home position, LA1 OFF, and the Original Cover closed?	YES	Check the photo receiver of PWB-H for contamination or replace PWB-H.
		NO	Replace PWB-A.