2-13. C0F20: AIDC Sensor UN3 Variation Correction Failure
C0F21: AIDC Sensor UN3 Contamination Correction Failure
C0F22: AIDC Sensor UN3 V_G Correction Failure
C0F23: AIDC Sensor UN3 Exposure Correction Failure

Symbol	Name
UN3	AIDC Sensor
PWB-A	Master Board



1136T024AA



1136C20TAA

Step	Check Item	Result	Action
1	Is PJ20AA plugged securely into PWB-A?	NO	Plug it in securely.
2	Is CN35 connected securely?	NO	Connect it securely.
3	Is UN3 installed at the correct position?	NO	Install it at the correct position.
4	Is the photo receiver or LED of UN3 dirty?	YES	Clean UN3.
		NO	Replace UN3 or PWB-A.