1156SBT040227A

27) C0F30: ATDC Sensor UN3 Failure
C0F31: ATDC Sensor UN3 Failure

Relevant Electrical Parts	
• ATDC Sensor UN3	• Master Board PWB-A



1156C19TAA

Step	Check Item	Result	Action
1	Is the malfunction code "C0F30" displayed?	YES	Go to step 3.
2	Is the value for "ATDC Ref. Value" of "Level History" equal to the value given on the Adjust Label?	NO	Enter the value given on the Adjust Label.
3	Is PWB-A PJ11A plugged in securely?	NO	Plug it in securely.
4	Is CN35 plugged in securely?	NO	Plug it in securely.
5	Is UN3 installed in the correct position?	NO	Reinstall.