(9) Smear on back

Section	Step	Check	Result	Action
Engine	1	Suction Belts are dirty.	YES	Clean.
	2	Image Transfer Corona is dirty.	YES	Clean.
	3	Pre-Image Transfer Guide Plate is dirty.	YES	Clean.
	4	Pre-Fusing Unit Guide Plate is dirty.	YES	Clean.
	5	Fusing Rollers is dirty.	YES	Clean or change.
	6	Toner spilled over area inside copier.	YES	Clean.

(10) Uneven image density

Section	Step	Check	Result	Action
Engine	1	PC Drum is properly grounded.	NO	Clean or change PC Drum Ground Plate.
	2	Comb Electrode and grid mesh are dirty and deteriorated.	YES	Clean or change.
	3	Image Transfer Corona is dirty and deteriorated	YES	Clean or change.
	4	Toner is even on Sleeve/Magnet Roller.	NO	Adjust DB. (See ADJUSTMENTS.) Correct developer conveying mechanism.
IR	1	Mirrors and lens are dirty.	YES	Clean.
	2	Exposure Lamp is dirty and deteriorated.	YES	Clean or change.