Step	Check Item	Result	Action
1	Does "C0200" remain shown even after the PC Drum Charge and Image Transfer/Paper Separator Coronas have been removed from the copier?	YES	Perform step 4.
2	Does "C0200" appear when the PC Drum Charge Corona is installed in the copier?	YES	Clean or replace the PC Drum Charge Corona.
3	Does "C0200" appear when the Image Transfer/Paper Separator Coronas are installed in the copier?	YES	Clean or replace the Image Transfer/Paper Separator Coronas.
4	Does "C0200" remain shown even after CN1 has been unplugged from HV1?	NO	Replace HV1.
		YES	Replace PWB-A.